

**STATEMENT OF WORK
TO INSPECT AND REPAIR ONLY AS NECESSARY
(IROAN) OF THE
NORTH FINDING MODULE,
MX-18204/GSQ,
NSN 6675-01-179-2982**

Prepared by:
Marine Corps Systems Command
Code CBG
814 Radford Blvd STE 20343
Albany, GA 31704-0343

TABLE OF CONTENTS

<u>Paragraph</u>	<u>Title</u>	<u>Page</u>
1.0	SCOPE	1
1.1	Background	1
2.0	APPLICABLE DOCUMENTS	1
2.1	Military Standard	1
2.2	Other Government Documents and Publications	1
2.3	Industry Standards	2
3.0	Requirements	2
3.1	General Tasks	2
3.2	Detailed Tasks	3
3.2.1	Phase I- Pre-Induction	3
3.2.2	Phase II- Repair	3
3.2.3	Phase III- Inspection, Testing, and Acceptance	4
3.2.4	Phase IV- Packing, Handling, Storage, and Transportation (PHS&T)	4
3.3	Government Furnished Equipment (GFE)/Government Furnished Materiel (GFM)	5
3.4	Contractor Furnished Materiel	5
3.5	Configuration Control	5
3.6	Electrostatic Discharge (ESD) Control Program	5
3.7	Quality Assurance Provisions	5
3.8	Acceptance	5
3.9	Rejection	6
4.0	REPORTS	6
4.1	Pre-Induction Checklist	6
4.2	Repairable Item Inspection Report	6
4.3	Monthly Progress Reports	6
Appendices		
Appendix A	DA Form 2404 (1 Apr 79)	A-1
Appendix B	Standard Form 364 (Rev. 2-80)	B-1

STATEMENT OF WORK

To Inspect and Repair Only as Necessary (IROAN) of the
NORTH FINDING MODULE, MX-18204/GSQ,
NSN: 6675-01-179-2982

1.0 SCOPE. This Statement of Work (SOW) establishes and sets forth tasks and identifies the work efforts that shall be performed by the Contractor to Inspect and Repair Only as Necessary (IROAN) the North Finding Module (NFM) MX-18204/GSQ, NSN 6675-01-179-2982, hereafter referred to as MX-18204/GSQ. This Document contains requirements to restore the MX-18204/GSQ to Condition Code "A." Condition Code "A" is defined as "serviceable/issuable without qualification, new, used, repaired or reconditioned materiel which is serviceable and issuable to all customers without limitation or restriction, including materiel with more than six months shelf-life remaining."

1.1 Background. IROAN is defined as "That maintenance technique which determines the minimum repairs necessary to restore equipment components or assemblies to prescribed maintenance serviceability standards by utilizing all available diagnostic equipment and test procedures in order to minimize disassembly and parts replacement."

2.0 APPLICABLE DOCUMENTS. The following documents form a part of this SOW to the extent specified. Unless otherwise specified, the issues of these documents are those listed in the DoD Index of Specifications and Standards (DoDISS) and supplement thereto which is in effect on the date of solicitation. In the event of conflict between the documents referenced herein and the contents of this SOW, the contents of this SOW shall be the superseding requirement.

2.1 Military Standard.

MIL-STD-129	DoD Standard Practice for Military Marking
-------------	--

2.2 Other Government Documents and Publications.

RS 08911A-50&P/3	Rebuild Standard With Illustrated Parts List North Finding Module MX-18204/GSQ
81A5034A0501/ CAGE 80372, Revision H	Display and Control Assy, A6, Engineering Drawing
81A5034A0200/ CAGE 80372, Revision L	Gyro and Case Assembly, Engineering Drawing
81A5034A0150/ CAGE 80372, Revision C	CPU and 12K Memory Assembly, A4, Engineering Drawing
81A5034A0130/ CAGE 80372, Revision P	Gyro Torquer Assembly, Engineering Drawing

81A5034A0120/ CAGE 80372, Revision J	Wheel and Servo Motor Supply Assembly, A2, Engineering Drawing
81A5034A0100/ CAGE 80372, Revision H	DC/DC Power Supply Assembly, Engineering Drawing
DoD 4000.25-1-M	MILSTRIP Manual
TM 08911A-34&P/2	Intermediate Maintenance Manual with Illustrated Parts List for North Finding Module MX-18204/GSQ

Military Handbooks (For Guidance)

MIL-HDBK-61	Configuration Management Guidance
-------------	-----------------------------------

2.3 Industry Standards.

JESD625-A	Requirements for Handling Electrostatic-Discharge-Sensitive (ESDS) Devices
ANSI/ISO/ASQC Q9002-1994	Quality Systems- Model for Quality Assurance in Production, Installation, and Servicing

Industry Standards (For Guidance)

ANSI/EIA-649	National Consensus Standard for Configuration Management
--------------	--

Copies of Military Specifications and Standards are available from the DoD Single Stock Point, Document Automation and Production Service, Building 4/D, 700 Robbins Avenue, Philadelphia, PA 19111-5094, telephone (215) 697-2179 or DSN 442-2179, or <http://www.dodssp.daps.mil>. Copies of other government documents and publications required by contractors in connection with specific SOW requirements shall be obtained through the Contracts Department (Code 891) P.O. Drawer 43019, 814 Radford Blvd., MCLB Albany, Georgia 31704-3019, commercial telephone number (229) 639-6761 or DSN 567-6761. Copies of engineering drawings, if applicable, shall be obtained from Supply Chain Management Center, Attn: Code 583-1, 814 Radford Blvd. Suite 20320, Albany, Georgia 31704-0320, commercial telephone number (229) 639-6410 or DSN 567-6410.

3.0 REQUIREMENTS.

3.1 General Tasks. In fulfilling the specified requirements, the Contractor shall provide materials, labor, equipment, facilities and missing/repair parts, necessary to inspect, diagnose,

restore and test and/or calibrate the MX-18204/GSQ. Upon completion of repairing the subject item, it shall be Condition Code "A".

3.2 Detailed Tasks. The following tasks describe the different phases for repair of the MX-18204/GSQ:

Phase I	Pre-Induction
Phase II	Repair
Phase III	Inspection, Testing, and Acceptance
Phase IV	Packaging, Handling, Storage and Transportation (PHS&T)

3.2.1 Phase I- Pre-Induction. The Contractor shall perform a Pre-Induction Inspection Analysis for each MX-18204/GSQ within 5 working days of induction into the Contractor's facility for evaluation of repair capability. If repair is not feasible, assign Condition Code "H" (CC "H"), notify Marine Corps Systems Command (MCSC), (Code CBG), Albany, GA., for disposition instructions, otherwise assign CC "M" and induct into the repair cycle. The Pre-Induction checklist, which consist of DA Form 2404 (Appendix A) and Standard Form 364 (Appendix B), shall be used to report all anomalies and shall be provided to the Government MCSC (Code CBG), Albany, GA., in accordance with Section 4.0 of this SOW.

3.2.2 Phase II – Repair. After Pre-Induction Tests and Inspections have been completed, repair of the MX-18204/GSQ shall be accomplished by the Contractor in accordance with this SOW. Deficiencies noted on the Pre-Induction Checklist (Appendix A and Appendix B) during Phase I shall be repaired/ replaced. Components or assemblies shall not be disassembled for replacement of parts unless that part has failed, or the component assembly wherein the part is located is disassembled for repair.

a. Hardware.

(1) Replace broken, unserviceable and/or missing hardware including nuts, bolts, screws, washers, turnlock fasteners, mandatory replacement items, safety and one-time use items. Unserviceable would include any of the above that failed to function properly.

(2) Ensure proper hardware locking devices are present on all moving mechanical assemblies.

(3) Hardware normally supplied with commercial parts shall be used unless specifically prohibited.

b. Publications and Documentation. The following standard, publication, and engineering drawings shall be used to assist the Contractor in restoring the MX-18204/GSQ to condition code "A".

RS 08911A-50&P/3

Rebuild Standard With Illustrated Parts List
North Finding Module MX-18204/GSQ

TM 08911A-34&P/2	Intermediate Maintenance Manual with Illustrated Parts List for North Finding Module MX-18204/GSQ
81A5034A0501/ CAGE 80372, Revision H	Display and Control Assy, A6, Engineering Drawing
81A5034A0200/ CAGE 80372, Revision L	Gyro and Case Assembly, Engineering Drawing
81A5034A0150/ CAGE 80372, Revision C	CPU and 12K Memory Assembly, A4, Engineering Drawing
81A5034A0130/ CAGE 80372, Revision P	Gyro Torquer Assembly, Engineering Drawing
81A5034A0120/ CAGE 80372, Revision J	Wheel and Servo Motor Supply Assembly, A2, Engineering Drawing
81A5034A0100/ CAGE 80372, Revision H	DC/DC Power Supply Assembly, Engineering Drawing

3.2.3 Phase III - Inspection, Testing and Acceptance.

- a. The Contractor shall conduct Inspection, Testing and Acceptance of the MX-18204/GSQ in accordance with the documents and TM listed in paragraph 3.2.2.b.
- b. The Contractor shall be responsible for conducting required tests in accordance with applicable procedures and specifications.
- c. The Contractor shall be responsible for correcting any deficiencies identified during inspection/testing. MCSC (Code CBG), Albany, GA., representatives may require the Contractor to repeat tests or portions thereof, if the original tests fail to demonstrate compliance with this SOW.

3.2.4 Phase IV - Packaging, Handling, Storage and Transportation (PHS&T).

- a. The Contractor shall be responsible for preservation and packaging of items being repaired under the terms of this statement of work. Preservation and packaging of items shall be in accordance with TM 08911A-34&P/2, paragraph 1-4.
- b. Marking for shipment and storage shall be in accordance with MIL-STD-129.
- c. The Marine Corps will provide the Contractor with the shipping address(es) for delivery of the repaired equipment, and the Contractor shall be responsible for arranging for

shipment to the pre-designated site(s). The Marine Corps will be responsible for transportation costs associated with shipping the subject equipment to and from the Contractor.

3.3 Government Furnished Equipment (GFE)/Government Furnished Materiel (GFM). The Management Control Activity (MCA/Code 573-2) will coordinate Government Furnished Equipment/Government Furnished Materiel (GFE)/(GFM) requests and maintain a central control system on all government owned assets in the contractor's possession. The MCA will forward a GFE Accountability Agreement to the contractor for signature on an annual basis to establish a chain of custody and identify property responsibilities for Marine Corps assets. The contractor is to acknowledge receipt of GFM to the MCA within 15 days of receipt. (This can be done by mailing (Materiel Management Department, Management Control Activity (Code 573-2) 814 Radford Blvd, STE 20320, Albany, GA 31704-0320) or faxing (commercial 229-639-5498 or DSN 567-5498) a copy of the DD1348).

3.4 Contractor Furnished Materiel (CFM). The Contractor may requisition materiel as required in the performance of the SOW through the DoD Supply System. DoD 4000.25-1-M (MILSTRIP) Chapter 11 provides guidance to contractors on the requisitioning process. The contractor's decision to utilize CFM procured from the DoD Supply System shall be based upon cost effectiveness, availability of materiel and the required completion/delivery date.

3.5 Configuration Control. The Contractor shall apply configuration control procedures to established configuration items. The Contractor shall not implement configuration changes to an item's documented performance or design characteristics without prior written authorization. If it is necessary to temporarily depart from the authorized configuration, the Contractor shall prepare and submit a Request for Deviation. MIL-HDBK-61 and ANSI/EIA-649 provide guidance for preparing these configuration control documents.

3.6 Electrostatic Discharge (ESD) Control Program. The Contractor shall establish, implement and document an ESD control program following the guidelines provided in JESD625-A. ESD protective measures shall be used during manufacturing, handling, inspection, testing, marking, packaging, storing and transporting ESD sensitive components.

3.7 Quality Assurance Provisions. The Contractor shall provide and maintain a quality system that as a minimum, adheres to the requirements of ANSI/ISO/ASQC Q9002-1994, Quality Systems-Model for Quality Assurance in Production, Installation and Servicing. The program shall ensure quality throughout all areas to include processing, assembly, inspection, testing, maintenance and preparation for delivery and shipping. Unless otherwise specified in the contract, the Contractor shall be responsible for performance of all inspection requirements. The Government, MCSC (Code CBG), Albany, GA., reserves the right to perform any of the inspections set forth in the contract where such inspections are deemed necessary to assure products and services conform to the prescribed requirements.

3.8 Acceptance. The performance of the Contractor and the quality of work delivered, including all equipment furnished and documentation written or compiled, shall be subject to in-process review and inspection during performance. Inspection may be accomplished in-plant or

at any work site or location, and Marine Corps, MCSC (Code CBG), Albany, GA., representatives shall be permitted to observe the work or to conduct an inspection.

3.9 Rejection. Failure to comply with any of the specified requirements listed herein shall be reason for rejection by MCSC (Code CBG), Albany, GA., representative. The Contractor shall, at no additional cost to MCSC (Code CBG), Albany, GA., correct the deficiencies and repeat the verification until an acceptable compliance with acceptance test procedures is demonstrated.

4.0 REPORTS.

4.1 Pre-Induction Checklist. The Contractor shall complete the Pre-Induction Inspection Checklist (Appendix A and Appendix B) for each MX-18204/GSQ repaired. These documents shall be available prior to final acceptance testing. One copy of each document shall be provided to Marine Corps Systems Command (Code CBG), 814 Radford Blvd., STE 20343, Albany, Georgia 31704-0343, after final acceptance of the MX-18204/GSQ.

4.2 Repairable Item Inspection Report. The Contractor shall provide a Repairable Item Inspection Report to Marine Corps Systems Command (Code CBG), 814 Radford Blvd., Suite 20343, Albany, Georgia 31704-0343 for each MX-18204/GSQ repaired. The report shall be identified by United States Marine Corps Serial Number.

4.3 Monthly Progress Reports. The Contractor shall provide Monthly Progress Reports summarizing the progress and status of the MX-18204/GSQ Program to Marine Corps Systems Command (Code CBG), 814 Radford Blvd., Suite 20343, Albany, Georgia 31704-0343.

[illegible]

INSTRUCTIONS

DEPARTMENT OF DEFENSE: DLAR 4140.55/AR 735.11.2/NAVSUPINST 4440.127E/AFR 400.54/MCO 4430.3E, Reporting of Item and Packaging Discrepancy and/or DLAR 4140.60/AR 12-12/NAVSUPINST 4920.9B/AFR 67.7/MCO 4140.1B, processing Discrepancy Reports Against Foreign Military Sales Shipments. CIVILIAN AGENCIES: See FPMR handbook cited in 19 (2) (a).

REPORT OF DISCREPANCY (ROD)				1. DATE OF PREPARATION		2. REPORT NUMBER <input type="checkbox"/>	
SHIPPING				PACKAGING			
3. TO: (Name and Address, Include ZIP Code)				4. FROM: (Name and Address, Include ZIP Code)			
<input type="checkbox"/>							
5a. SHIPPERS NAME				5b. NUMBER AND DATE OF INVOICE		5c. TRANSPORTATION DOCUMENT NUMBER (GBL, Waybill, TCN, etc.)	
7a. SHIPPER'S NUMBER (Purchase Order/Shipmet, Contract, etc)				7b. OFFICE ADMINISTERING CONTRACT		8. REQUISITIONER'S NUMBER (Requisition, Purchase, etc.)	
9. SHIPMENT, BILLING, AND RECEIPT DATA						10. DISCREPANCY DATA	
NSN/PART NUMBER AND NOMENCLATURE		UNIT OF ISSUE	QUANTITY SHIPPED/ BILLED	QUANTITY RECEIVED	QUANTITY	UNIT PRICE	TOTAL COST
(a)		(b)	(c)	(d)	(a)	(b)	(c)
12. REMARKS (continue on separate sheet of paper if necessary)							

1. DISCREPANCY CODES		2. ACTION CODES	
<p>CONDITION OF MATERIAL</p> <p>C1 - In condition other than that indicated on release/receipt document</p> <p>C2 - Expired shelf life</p> <p>C3 - Damaged parcel post shipment</p> <p>SUPPLY DOCUMENTATION</p> <p>D1 - Not received</p> <p>D2 - Illegible or mutilated</p> <p>D3 - Incomplete, improper or without authority (Only when receipt cannot be properly processed)</p> <p>MISDIRECTED MATERIAL</p> <p>M1 - Addressed to wrong activity</p> <p>OVERAGE/DUPLICATE SHIPMENTS</p> <p>O1 - Quantity in excess of that on receipt document</p> <p>O2 - Quantity in excess of that requested (Other than unit of issue pack)</p> <p>O3 - Quantity duplicate shipment</p> <p>PACKING DISCREPANCY</p> <p>P1 - Improper preservation</p> <p>P2 - Improper packing</p> <p>P3 - Improper Marking</p> <p>P4 - Improper unitization</p>		<p>PRODUCT QUALITY DEFICIENCIES</p> <p>Q1 - Deficient material (Applicable to Grant Aid and FMS shipments)</p> <p>SHORTAGE OF MATERIAL</p> <p>S1 - Quantity less than that on receipt document</p> <p>S2 - Quantity less than that requested (Other than unit of issue pack)</p> <p>S3 - Non-receipt of parcel post shipments</p> <p>ITEM TECHNICAL DATA MARKINGS (i.e., Name Plates, Log Books, Operating Handbooks, Special Instructions, etc.)</p> <p>T1 - Missing</p> <p>T2 - Illegible or Mutilated</p> <p>T3 - Precautionary operational markings missing</p> <p>T4 - Inspection data missing or incomplete</p> <p>T5 - Serviceability operating data missing or incomplete</p> <p>T6 - Warranty data missing</p> <p>WRONG ITEM (Identify requested item as a separate copy in Item 9. above)</p> <p>W1 - Incorrect item received</p> <p>W2 - Unacceptable substitute</p> <p>OTHER DISCREPANCIES</p> <p>Z1 - See Remarks</p>	
<p>1A - Disposition instructions requested (Reply or)</p> <p>1B - Material being retained (See Remarks)</p> <p>1C - Supporting supply documentation requested</p> <p>1D - Material still required, expedite shipment (if applicable to FMS)</p> <p>1E - Local purchase material to be returned at su expense unless disposition instructions to the contra are received within 15 days (Reply on reverse) (Not applicable to FMS)</p> <p>1F - Replacement shipment requested (Not appl. FMS)</p> <p>1G - Reshipment not required. Item to be re-req</p> <p>1H - No action required. Information only</p> <p>1Z - Other action requested (See remarks)</p>			

13. FUNDING AND ACCOUNTING DATA	
14a. TYPED OR PRINTED NAME, TITLE, AND PHONE NUMBER OF PREPARING OFFICIAL	14b. SIGNATURE <input type="checkbox"/>
15. DISTRIBUTION ADDRESSEES FOR COPIES	

364-103	7540-00-159-4442	(Previous edition is obsolete)	STANDARD FORM 364 (Rev. Prescribed by GSA FP)
---------	------------------	--------------------------------	---

16. FROM:	17. DISTRIBUTION ADDRESSEES FOR DISTRIBUTION
18. TO:	Use window envelope to mail this document. Insert Name and address, including ZIP Code, starting one typing space below the left dot. Each address line must

		NOT extend beyond right dot. Address must not exceed four single space typing lines.	
19. IN ACCORDANCE WITH NOTICE OF DISCREPANCY ON FACE OF THIS FORM:			
a. MATERIAL <input type="checkbox"/> HAS BEEN <input type="checkbox"/> WILL BE SHIPPED		DOCUMENT NUMBER	
c. <input type="checkbox"/> AN ADJUSTMENT IN BILLING HAS BEEN/WILL BE PROCESSED AS A <input type="checkbox"/> CREDIT <input type="checkbox"/> DEBIT		b. <input type="checkbox"/> NO RECORD OF SHIPMENT. RESUBMIT REPORT TO PROPER OFFICE UNDER d. <input type="checkbox"/> INVOICE/BILL ATTACHED e. <input type="checkbox"/> PROOF OF DELIVERY	
f. <input type="checkbox"/> AN ADJUSTMENT IN BILLING FOR THIS REPORTED DISCREPANCY WILL NOT BE PROCESSED FOR THE FOLLOWING REASON WHICH IS CITED IN THE INDICATED REGULATION			
(1) REASON FOR NOT PROCESSING		(2) PRESCRIBING REGULATION	
<input type="checkbox"/> (a) DISCREPANCY WAS NOT REPORTED WITHIN THE TIME FRAMES ALLOWED AND/OR		<input type="checkbox"/> (a) CHAPTER 5 OF THE GSA HANDBOOK, DISCREPANCIES OR DEFICIENCIES IN GSA OR DOD SHIPMENTS, MATERIALS, OR BILLINGS (FPMR 101.26.8)	
<input type="checkbox"/> (b) DOLLAR VALUE DOES NOT MEET THE CRITERIA PRESCRIBED IN THE REGULATION OR AGREEMENT INDICATED IN 191(2)		<input type="checkbox"/> (b) CHAPTER 2 AND/OR 7 OF DOD 4000.25.7.M, MILITARY STANDARD BILLING SYSTEM (MILBILLS) AND/OR DD 1513, U.S. DOD OFFER AND ACCEPTANCE, AS APPLICABLE	
20. THE FOLLOWING DISPOSITION IS TO BE MADE OF THE REFERENCED MATERIAL			
a. <input type="checkbox"/> PROCESS FOR DISPOSAL IN ACCORDANCE WITH SERVICE/AGENCY DIRECTIVES		b. <input type="checkbox"/> REPRESENTATIVE WILL CALL FOR DISCUSSION CONCERNING DISPOSITION	
c. <input type="checkbox"/> RETAIN MATERIAL AT NO CHARGE		d. <input type="checkbox"/> MATERIAL WILL BE PICKED UP IN:	
e. <input type="checkbox"/> SHIP MATERIAL <i>Specify location</i>		DAYS	
(1) <input type="checkbox"/> GBL APPROPRIATION CHARGEABLE:		DAYS	
(2) <input type="checkbox"/> CHARGES COLLECT - VIA: <input type="checkbox"/> FREIGHT <input type="checkbox"/> EXPRESS <input type="checkbox"/> PARCEL POST		(\$	
(3) <input type="checkbox"/> PARCEL POST LABEL ATTACHED		(4) <input type="checkbox"/> FREIGHT PREPAID	
f. <input type="checkbox"/> OTHER <i>(Specify)</i>			
21. <input type="checkbox"/> IF MATERIAL IS STILL REQUIRED, SUBMIT NEW REQUISITION.		22. <input type="checkbox"/> REPLACEMENT WITH SATISFACTORY MATERIAL WILL BE MADE ON/OR BEFORE:	
23. REMARKS <i>(Continue on separate sheet of paper if necessary).</i>			
24a. TYPED OR PRINTED NAME AND PHONE NUMBER OF PREPARING OFFICIAL		24b. SIGNATURE	
		24c. DATE	

STANDARD FORM 364 BACK (REV. 2-80)

CONTRACT DATA REQUIREMENTS LIST

(1 Data Item)

Form Approved
OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 110 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0701-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. Please DO NOT RETURN your form to the above address. Send completed form to the Government Issuing Contracting Officer for the Contract/PR No. listed in Block E.

A. CONTRACT LINE ITEM NO.	B. EXHIBIT	C. CATEGORY: TDP _____ TM _____ OTHER <input checked="" type="checkbox"/>
---------------------------	------------	--

D. SYSTEM/ITEM North Finding Module, MX-18204/GSQ	E. CONTRACT/PR NO.	F. CONTRACTOR
--	--------------------	---------------

1. DATA ITEM NO. A001	2. TITLE OF DATA ITEM Contractor's Progress, Status, and Management Report	3. SUBTITLE Management
--------------------------	---	---------------------------

4. AUTHORITY (Data Acquisition Document No.) DI-MGMT-80227	5. CONTRACT REFERENCE SOW 4.3	6. REQUIRING OFFICE MCSC (CBG), Albany, GA
---	----------------------------------	---

7. DD 250 REQ LT	9. DIST STATEMENT REQUIRED A	10. FREQUENCY MTHLY	12. DATE OF FIRST SUBMISSION See Blk 16	14. DISTRIBUTION												
8. APP CODE A	11. AS OF DATE	13. DATE OF SUBSEQUENT SUBMISSION See Blk 16	<table border="1"> <tr> <th>a. ADDRESSEE</th> <th colspan="3">b. COPIES</th> </tr> <tr> <th></th> <th>Draft</th> <th>Reg</th> <th>Final</th> </tr> <tr> <td>MCSC (CBG) Albany, GA</td> <td>0</td> <td>1</td> <td>0</td> </tr> </table>		a. ADDRESSEE	b. COPIES				Draft	Reg	Final	MCSC (CBG) Albany, GA	0	1	0
a. ADDRESSEE	b. COPIES															
	Draft	Reg	Final													
MCSC (CBG) Albany, GA	0	1	0													

16. REMARKS Contractor format is authorized. Blk 4 - Tailor DI-MGMT-80227 as follows: Delete paragraphs 10.3g, 10.3h, 10.3i, and 10.3j. Blk 12 - The reporting period shall be from the first to last business day of each month. Initial submission shall be 60 DAC. Blk 13 - Subsequent submissions shall be 10 days after the last business day of each month. Distribution StatementA: Approved for public release; Distribution is unlimited.	15. TOTAL		
	0	1	0

G. PREPARED BY <i>Samuel Taylor</i>	H. DATE 10/11/01	I. APPROVED BY <i>Samuel Taylor</i>	J. DATE 10/11/01
--	---------------------	--	---------------------

17. PRICE GROUP
18. ESTIMATED TOTAL PRICE

CONTRACT DATA REQUIREMENTS LIST

(1 Data Item)

Form Approved
OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 110 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0701-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. Please DO NOT RETURN your form to the above address. Send completed form to the Government Issuing Contracting Officer for the Contract/PR No. listed in Block E.

A. CONTRACT LINE ITEM NO.	B. EXHIBIT	C. CATEGORY: TDP _____ TM _____ OTHER <input checked="" type="checkbox"/>
---------------------------	------------	--

D. SYSTEM/ITEM North Finding Module, MX-18204/GSQ	E. CONTRACT/PR NO.	F. CONTRACTOR
--	--------------------	---------------

1. DATA ITEM NO. B001	2. TITLE OF DATA ITEM Repairable Item Inspection Report	3. SUBTITLE Integrated Logistics Support
--------------------------	--	---

4. AUTHORITY (Data Acquisition Document No.) DI-ILSS-80386	5. CONTRACT REFERENCE SOW 4.2	6. REQUIRING OFFICE MCSC (CBG), Albany, GA
---	----------------------------------	---

7. DD 250 REQ LT	8. DIST STATEMENT REQUIRED A	9. FREQUENCY ASREQ	10. DATE OF FIRST SUBMISSION 60 DAC	11. AS OF DATE	12. DATE OF SUBSEQUENT SUBMISSION See Blk 16	13. DISTRIBUTION								
14. APP CODE A						<table border="1"> <tr> <th>a. ADDRESSEE</th> <th colspan="3">b. COPIES</th> </tr> <tr> <th></th> <th>Draft</th> <th>Reg</th> <th>Repro</th> </tr> </table>	a. ADDRESSEE	b. COPIES				Draft	Reg	Repro
a. ADDRESSEE	b. COPIES													
	Draft	Reg	Repro											

16. REMARKS Blk 4 - Contractor format is authorized. Blks 10 - A separate report shall be submitted for each North Finding Module, MX-18204/GSQ repaired. Blks 12 & 13 - Submit report by Marine Corps Serial Number 30 days after completion of each North Finding Module, MX-18204/GSQ. Distribution Statement A. Approved for Public Release; Distribution is unlimited.	MCSC (CBG)	0	1	0	
	Albany, GA				
	15. TOTAL		0	1	0

G. PREPARED BY <i>Barrell Taylor</i>	H. DATE 10/11/01	I. APPROVED BY <i>Barrell Taylor</i>	J. DATE 10/11/01
---	---------------------	---	---------------------

17. PRICE GROUP
18. ESTIMATED TOTAL PRICE

(1 Data Item)

Form Approved
OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 110 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0701-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. Please DO NOT RETURN your form to the above address. Send completed form to the Government Issuing Contracting Officer for the Contract/PR No. listed in Block E.

A. CONTRACT LINE ITEM NO.	B. EXHIBIT	C. CATEGORY: TDP _____ TM _____ OTHER _____ X
----------------------------------	-------------------	--

D. SYSTEM/ITEM North Finding Module, MX-18204/GSQ	E. CONTRACT/PR NO.	F. CONTRACTOR
---	---------------------------	----------------------

1. DATA ITEM NO.	2. TITLE OF DATA ITEM	3. SUBTITLE
C001	Request For Deviation	Configuration Management

4. AUTHORITY (Date Acquisition Document No.) DI-CMAN-80640C	5. CONTRACT REFERENCE SOW 3.5	6. REQUIREMENT OFFICE MCLBA (583)
---	---	---

7. DO 256 REQ LT	8. DIST STATEMENT REQUIRED A	10. FREQUENCY ASREQ	12. DATE OF FIRST SUBMISSION See Blk 16	14. DISTRIBUTION		
11. AS OF DATE		13. DATE OF SUBSEQUENT SUBMISSION See Blk 16	a. ADDRESSEE	Draft	b. COPIES Final	
9. APP CODE A						

[illegible]

G. PREPARED BY <i>James C. Clark</i>	H. DATE <i>9/25/01</i>	I. APPROVED BY <i>Samuel Taylor</i>	J. DATE <i>10/11/01</i>
---	---------------------------	--	----------------------------